0010



State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING



gh

Michael O. Leavitt Governor

Ted Stewart Executive Director James W. Carter

James W. Carter Division Director

 1594 West North Temple, Suite 1210

 Box 145801
 Partial: XXX Complete: Exploration: Exploration: Market City, Utah 84114-5801 Inspection Date & Time: 4/21/98 / 8:00a.m.-12:00p.m.

 (801) 538-5340
 Date of Last Inspection: 3/25/98

Mine Name: Bear Canyon Mine County: Emery Permit Number: ACT/015/025						
Permittee and/or Operator's Name: Co-Op Mining Company						
Business Address: P. O. Box 1245, Huntington, Utah 84528						
Type of Mining Activity: Underground XXX Surface Prep. Plant Other						
Company Official(s): Marlo Petersen						
State Officials(s): Peter Hess Federal Official(s): None						
Weather Conditions: Warm, 50's						
Existing Acreage: Permitted-1032.75 Disturbed-24 Regraded-0 Seeded-0 Bonded-24						
Increased/Decreased: Permitted Disturbed Regraded Seeded Bonded						
Status: _Exploration/_XXX_Active/Inactive/_Temporary Cessation/_Bond Forfeiture						
Reclamation (_Phase I/_Phase II/_Final Bond Release/_LiabilityYear)						

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENIS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	Ц	\Box		
2.	SIGNS AND MARKERS	[XX]	\Box	\Box	\Box
3.	TOPSOIL	[XX]	Ш	\Box	\Box
4.	HYDROLOGIC BALANCE:	<u></u>			
a.	DIVERSIONS	[XX]	\Box	\Box	\Box
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[XX]	ĹÌ	[XX]	\Box
c.	OTHER SEDIMENT CONTROL MEASURES	[XX]	\Box	\Box	\Box
d.	WATER MONITORING		Ш	\Box	\Box
e.	EFFLUENT LIMITATIONS		\Box	\Box	\Box
5.	EXPLOSIVES			\Box	
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	\Box	[XX]		ĹÌ
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	\Box	Ц	ĹĬ	Ш
8.	NONCOAL WASTE	[XX]		ĹÌ	\Box
9.	PROTECTION OF FISH, WILDLIFE AND				
	RELATED ENVIRONMENTAL VALUES	[XX]	Ш	[XX]	\Box
0.	SLIDES AND OTHER DAMAGE	Ш	[XX]	\Box	\Box
1.	CONTEMPORANEOUS RECLAMATION	\Box		П	\Box
2.	BACKFILLING AND GRADING	ĹÌ	[XX]	\Box	\Box
13.	REVEGETATION	\Box	[XX]	Ц	\Box
١4.	SUBSIDENCE CONTROL	ĹĬ	\Box	\Box	\Box
l 5 .	CESSATION OF OPERATIONS	Ū	[XX]	\Box	\Box
l 6 .	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	\Box	\Box	\Box	\Box
b.	DRAINAGE CONTROLS	[XX]	\Box	\Box	\Box
١7.	OTHER TRANSPORTATION FACILITIES	\Box	\Box	\Box	
l8.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[XX]	\Box	\Box	\Box
19.	AVS CHECK (4th Quarter-April, May, June)(date)	Ш	Ш	\Box	\Box
20.	AIR QUALITY PERMIT	[XX]	ЦÌ	[XX]	\Box
21.	BONDING & INSURANCE	[]	ĪĪ	[1]	\Box



INSPECTION REPORT

(Continuation sheet)

Page <u>2</u> of <u>2</u>

PERMIT NUMBER: ACT/015/025

DATE OF INSPECTION: 4/21/98

(Comments are Numbered to Correspond with Topics Listed Above)

4b. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The permittee was in the process of cleaning pond "B" at the onset of this inspection. This job appeared to be nearly completed. The sediment clean out material is being stored in the truck loading area until it dries. The material will then be used as fill to expand the stockpile pad. When the pond capacity is determined to have sufficient volume, pond "B" will be re-certified.

9. PROTECTION OF FISH, WILDLIFE, AND RELATED ENVIRONMENTAL VALUES

During the inspection of the maintenance shop area, the following items were noted:

- 1) A Chevrolet pickup truck that is being parted-out contained two old batteries. The permittee needs to properly store and/or dispose of these. Mr. Petersen immediately notified shop personnel to take care of this.
- There is a cement pad behind the shop that is used to store hydraulic components that are to be rebuilt. Oil has been allowed to drain from these components, and pollute the ground around the pad. Mr. Petersen was instructed to clean up the contaminated soil and properly dispose of it. It was also suggested that a berm be placed around the pad to contain any future spills.

20. AIR QUALITY PERMIT

The permittee's water truck was observed wetting the mine's access roads during the inspection.

The coal storage piles appeared damp this day.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.						
Copy of this Report:						
Mailed to: <u>Charles Reynolds (Co-Op)</u> Given to: <u>Joe Helfrich (DOGM)</u> Date: <u>April 22, 1998</u>	Henry Austin (OSM) Filed to: Price Field Office					
Inspector's Signature: The Less	#46					

Peter Hess